SAFE JOB PROCEDURES 4.17

JOB TITLE: DRYWALL DUST

DEVELOPED BY: Jennifer Moher DATE: February 19, 2008

APPROVED BY: Dan Sager POSITION: Safety Coordinator

DATE: <u>April 3, 2008</u>

REVISED BY: Mario Marier DATE: October 22/09

EQUIPMENT REQUIRED: Dust mask, eye protection, gloves

MATERIAL REQUIRED: MSDS

PERSONAL PROTECTIVE EQUIPMENT: Steel-toed boots and hard hats.

JOB STEPS:

1. Read the WHIMS information for drywall where there is a likelihood of exposure to drywall dust. Be aware of hazards associated with drywall.

- 2. Read the WHMIS information for drywall mud where there is a likelihood of exposure to mud dust. Be aware of hazards associated with mud compounds.
- Ensure the site is well ventilated.
- 4. Ensure the work area is free of all debris before commencing work, as vision will be obscured in dusty areas.
- 5. Ensure all guard rails are in place and all holes in the floor are covered before work starts.
- 6. Be aware of the locations plumbing, piping, etc. protruding from floors or walls cover or barricade off if possible.
- 7. Seek immediate medical assistance if you have difficulty seeing, shortness of breath, constant irritation, persistent cough, nausea or dizziness.
- 8. Notify your supervisor of any medical issues you are having.
- 9. All sanding must be swept up with a broom when finished to avoid housekeeping incidents.
- 10. If you get dust or debris in your eyes, seek out an eye washing station and report to the supervisor.